

SERVICE BULLETIN

DOC NO.: 46970

DATE: 07/06/2017

PRODUCT: LX PYRO

COMBISTEAMER OVEN

Products concerned: DOS7585X

After sales instructions: If removing the spreader, the spreader grill seal AS0066375 must always be replaced.

Oven with spreader removed:



Seal must be replaced.

